

707/3



08803814.022497




FIG. 1

14

2004-08-20 11:18:00




Figure 2A




Figure 2B






Fig. 3 Contact Card structure

08303814.022497

200303844-02497






Fig. 20 Two search characters has been provided




Fig. 21 No matching contacts

Telefax

Anderson Pieler

Percovic Andrew

Twinsor-Jockston Aнна

25

Pick Ltd.

AA Companies, Inc.

Fenton Images Corp.

an

21

Search

Call ☐

Enter number ☐

Recent calls ☐

Settings ☐

One matching contact does not have telefax number specified

300

FIG. 5A

E-Mail directory

Adolfson Jack

Anderson Pieler

Benson William

Lukather Stephen

Percovic Andrew

Savolainen Asser

Twinsor-Jockston Anna

28

United Jacks, Inc.

Pick Ltd.

A/S Norton

Reel-In Corp.

AA Companies, Inc.

Befel Johnson & Co.

Fenton Images Corp.

Search

Select ☐

Enter address ☐

Cancel ☐

E Mail directory, sorted by Name field

400

FIG. 5B

00003814-002497




FIG. 6A




FIG. 6B




FIG. 7B




FIG. 7A